



**SAVING LIVES
AND
PROTECTING
PROPERTY**

WWW.MONTGOMERY.NJ.US

Municipal Building
2261 Van Horne Road
(Route 206)
Belle Mead, New Jersey 08502
(908) 359-8211
FAX (908) 359-2006

Bureau of Fire Prevention
Roy Mondri

Business/Organization: _____

Address: _____

Month: _____

Carbon Monoxide Detection Testing Log								
Device ID #	Date Device Tested	Type of Device P = Plug-In Type B = Battery Operated H = Hardwired C = Combo	Location	Person Performing Test	Results 1 = Pass 2 = Fail R = Replaced	Date Repaired	Type of Repair 1 = Battery Replaced 2 = Unit Replaced 3 = Other	Person Verifying Repair Has Been Made
1	01-10-2017	B	Boiler Room (Near Entrance)	John Doe	1	N/A	N/A	N/A

NFPA 720: 8.7.1 Single- and multiple-station carbon monoxide alarms and all connected appliances shall be inspected and tested in accordance with the manufacturer's published instructions at least monthly.
NFPA 720: 8.8.1.1 Household carbon monoxide detection systems shall be tested by a qualified service technician at least every 3 years according to the methods in Table 8.4.3